Message

From: Lobik Stephen [slobik@facil.umass.edu]

Sent: 2/29/2012 1:26:50 PM

To: Hanchett, James (DPH) [/O=COMMONWEALTH OF MASSACHUSETTS/OU=MassMail-

01/cn=Recipients/cn=James.Hanchett]

Subject: RE: AC/Heating Unit

Jim,

Is there a time I can take a look? What JCI is mentioning doesn't make sense to me.

Stephen

Stephen Lobik
Capital Project Manager
Facilities Planning Division
University of Massachusetts
(T) 413-545-6516

(C)

(F) 413-545-3684

slobik@facil.umass.edu

From: Hanchett, James (DPH) [mailto:james.hanchett@state.ma.us]

Sent: Wednesday, February 29, 2012 8:17 AM

To: Lobik Stephen

Subject: AC/Heating Unit

Hi Steve,

I had a guy from Johnson Controls look at our heating unit. There is not enough pressure to push condensate up 18 inches. It does not help to increase steam pressure because control valves will throttle it down. The solution is to not push condensate up 18 inches of pipe. Smallest amount is best. What can be done?

Jim Hanchett Amherst Drug Lab Room N251 Morrill I 637 North Pleasant Street Amherst, MA 01003 Phone 413-545-2607 Fax 413-545-2608 Cell

Folk_OIG_PRR_095666